


















Pressix CC 41

Det effektiva montagesystemet

RSK nr	Benämning:	Antal/förp.	Pressix CC 41
3820086	Montageskena 41/21/1,5 fzb L=6m	1	
3820786	Montageskena 41/21/1,5 fzb L=2m	1	
26504	Montageskena 41/21/1,5D fzb L=2m	1	
3820787	Montageskena 41/21/2,5 fzb L=2m	1	
26501	Montageskena 41/21/2,5 fzb L=3m	1	
3820788	Montageskena 41/41/2,5 fzb L=2m	1	
26507	Montageskena 41/41/2,5 fzb L=3m	1	
3820789	Montageskena 41/41/2,5 fzb L=6m	1	
3820790	Ändstycke 41/21 gul	100	
3820791	Ändstycke 41/41 gul	100	
3820793	Pressix konsol 41/41 -200 fzb	10	
3820794	Pressix konsol 41/41 -260 fzb	10	
3820795	Pressix konsol 41/41 -320 fzb	10	
3820796	Pressix konsol 41/41 -445 fzb	10	
3820797	Pressix konsol 41/41 -570 fzb	10	
3820798	Pressix konsol 41/41 -820 fzb	1	
3820798	Pressix konsol 41/41 -1020 fzb	1	
3820799	Pressix konsolfot MH 41 fzb	10	 <p style="text-align: center;">MV MH</p>
3820801	Pressix konsolfot MV 41 fzb	10	
26840	Skenbygel SH 41/21 fzb	50	
26842	Skenbygel SH 41/41 (41/21D) fzb		
26768	Hörnkonsol EW 41 fzb	25	
	Balkbygel 41 M8 fzb	20	
	Balkbygel 41 M10 fzb	20	
	Balkbygel 41-D M10 fzb	20	
3820802	Skenfot WBD 41/21 fzb	10	
3820803	Skenfot WBD 41/41 fzb	10	
26799	Klämkonsol SKL	5	










Pressix CC 41

Det effektiva montagesystemet

RSK nr	Benämning:	Antal/förp.	Pressix CC 41
26776 26777	Skenfot SHB-dämp 41- 1 FZV Skenfot SHB-dämp 41- 2 FZV	10 5	
9189740	Skenteleskop 41 - M10	10	
3820804 3820805 3820806	Fjädermutter CC M 6 fzb Fjädermutter CC M 8 fzb Fjädermutter CC M 10 fzb Fjädermutter CC M 12 fzb Fjädermutter CC M 16 fzb	50 50 50 50 50	
26516	Profilmutter HZ 41 M 8 fzb Profilmutter HZ 41 M 10 fzb Profilmutter HZ 41 M 12 fzb Profilmutter HZ 41 M 16 fzb	50 50 50 50	
	Profilmutter 41 M8 fzb Profilmutter 41 M10 fzb	50 50	
3820807 3820808 3820809	Profilbricka B41/10 fzb Profilbricka B41/12 fzb Profilbricka B41/16 fzb	50 50 50	
3820106 3820091 26521	Fjäderblock 41 M8 fzb Fjäderblock 41 M10 fzb Fjäderblock 41 M12 fzb	50 50 50	
3820810 3820811 3820812	Fjäderblock PBH 41 M 8 fzb Fjäderblock PBH 41 M 10 fzb Fjäderblock PBH 41 M 12 fzb	50 50 50	
3820138 3820139 3820140 3820141 3820142 3820143 3820144 3820145 3820146 3820147	Blockset CC 41 M8x 35 fzb Blockset CC 41 M8x 75 fzb Blockset CC 41 M8x 125 fzb Blockset CC 41 M8x 175 fzb Blockset CC 41 M8x 275 fzb Blockset CC 41 M10x 35 fzb Blockset CC 41 M10x 75 fzb Blockset CC 41 M10x 125 fzb Blockset CC 41 M10x 175 fzb Blockset CC 41 M10x 275 fzb	25 25 25 25 25 25 25 25 25 25	

Pressix CC 41

Det effektiva montagesystemet

RSK nr	Benämning:	Antal/förp.	Pressix CC 41
26864 26865 26866	Skenanslutning CC 41-1 Skenanslutning CC 41-2 Skenanslutning CC 41-3	20 10 10	
26867 26868 26869	Vinkelanslutning CC 41 -90° Vinkelanslutning CC 41 -3 Vinkelanslutning CC 41 -4	25 10 10	 90° 3 4
9190658	Glidstycke 41	10	
9191711 9191729 9191747 9191738	Glidstöd CC 41 - 2G -1 M10/M16 Glidstöd CC 41 - 2G -2 M10/M16 Glidstöd CC 41 - 3G -1 M12/16/1/2" Glidstöd CC 41 - 3G -2 M12/16/1/2"	25 25 10 10	
3820117 3820118	Pressix pendelstång M8x1000 fzb Pressix pendelstång M10x1000 fzb	25 25	
26523	Montagesats KL 1	50	
9110879	Skenclips för kabel	500	
26698	Dämelement CC 41 M8/M10	100	
26678	Dämpgummi 41	30m/rulle	
3820103	Pressix gängstångsklipp	1	